



## Switch

Method	Wheelchair	Lockdown/Suitable
<b>Rear Wheel Drive</b>	<b>Invacare</b>	
	Storm 4	Not Suitable
	Spectra XTR	Q'Straint QLK 100
	Spectra Plus	Q'Straint QLK 100
	Topan	Q'Straint QLK 100
	Stream	Q'Straint QLK 100
	Mirage	Q'Straint QLK 100
<b>Centre Drive</b>	<b>Invacare</b>	
	TDX	Not Suitable
	Typhoon 2	Not Suitable
	Tornado	Not Suitable
<b>Front or Rear Wheel Drive</b>	<b>Handicare</b>	
	Beatle	New chair set up with reinforced battery box will suit vehicle and will fit with QLK 100
<b>Rear Wheel Drive</b>	<b>Sunrise</b>	
	Salsa	Not Suitable
	Rumba	Q'Straint QLK 100
	F40VR	Q'Straint QLK 100
	Ibis	Not Suitable
<b>Centre Drive</b>	<b>Sunrise</b>	
	Groove	Q'Straint QLK 100
<b>Centre Drive</b>	<b>Pride</b>	
	Q600 and Q610	Dock and Lock
	Jazzy 1121 and 1103	Not Suitable
<b>Centre Drive</b>	<b>ETAC</b>	
	Balder	Balder Spigot
<b>Rear Wheel Drive</b>	<b>Auto Adapt</b>	
	Carony Drive	Carony Drive Lock
	<b>Permobil</b>	
	C300 and C400 and C500	These need to be checked

**ALWAYS REMEMBER THAT THE HEIGHT OF THE CUSTOMER MUST BE TAKEN INTO CONSIDERATION**